

Date: 16 November, 2001
Re: Sony Corporation
FCC ID: AK8TMRR90

Dear Mr. Timothy Johnson,

Please find the following replies to your comments (110701);

- 1) We uploaded it. Please find our revised test report (No.: 22CE0008-YW-1) in the filing. We corrected item 4.2 in the report.
- 2) We uploaded it. Please find the revised photos in the filing.
- 3) Regarding to Carrier level, we performed the testing by no modulation because there was not the difference between modulation and no modulation. Please find the carrier data in the filing.
- 4) We uploaded it. Please find the revised photos in the filing.
- 5) The carrier level always becomes stable between 85 to 115 % of input voltage. Also, the frequency didn't change. Please find the data in the filing.

Kanako Sanda
A-Pex International Co., Ltd.