

From: Jackie Pillai <jackie@mflom.com>  
Subject: Kenwood ALH378400 ATCB005114  
To: Tim Johnson <tjohnson@atcb.com>



**Flom Test Labs**  
EMI, EMC, RF Testing Experts Since 1963

toll-free: (866) 311-3268  
fax: (480) 926-3598  
[www.flomlabs.com](http://www.flomlabs.com)  
[info@flomlabs.com](mailto:info@flomlabs.com)

Dear Tim,

In response to your questions:

1. Client has been submitting these types of photos for all previous applications. Client has been advised that, in the future, he provides more photos.
2. Client has been submitting same type of label for years. Unless there are new IC requirements, there is no need to change them.
3. See revised report - uploaded.
4. See revised report - uploaded.
5. See revised report - uploaded.
6. Is an FYI only.
7. See revised IC application.
8. See revised report - uploaded.
9. See revised report - uploaded.
10. No, the device does not use any scrambling techniques.
11. Form 731 is correct, typo in test report corrected. See revised report - uploaded.
12. Client has been submitting applications for years using these rules sections.
13. Same answer as #12.
14. 90.203 attestation uploaded.
15. Cross reference uploaded.
16. User programming is not accessible. See exhibit from #14.
17. Cross reference uploaded.
18. Waiting for TCB response.
19. Device connector is not used as a data modem.
20. Waiting for TCB response.

If you have any questions, please feel free to contact us.

Regards,

Jackie Pillai  
Administration  
Phone: (480) 926-3100

Confidential - The information in this message is only intended for the person(s) or organization(s) to whom it is addressed. If you are not that person, please contact the sender, and destroy this copy.

