



**INTERNAL PHOTOGRAPH SECTION
FOR RFI TEST REPORT SERIAL NO:
RFI/MPTB2/45184JD05A**

Test Of: Ericsson AB.
RBS 2308 850 MHz R5B

To: FCC Part 22: 2002

Radio Frequency Investigation Ltd, Ewhurst Park, Ramsdell,
Basingstoke, Hampshire, RG26 5RQ, ENGLAND.
Tel: +44 (0) 1256 851193 Fax: +44 (0) 1256 851192

Registered in England, No. 211 7901.
Registered Office: Ewhurst Park, Ramsdell,
Basingstoke, Hampshire RG26 5RQ



Test Of: Ericsson AB.
RBS 2308
To: FCC Part 22: 2002

Photographs of EUT

This section contains the following photographs:

Photo Reference Number	Title
PHT/45184JD05/001	Open view of RRU-M EDGE
PHT/45184JD05/002	Front view of Radio Access Board 1
PHT/45184JD05/003	Back view of Radio Access Board 1
PHT/45184JD05/004	Front view of Radio Access Board 2
PHT/45184JD05/005	Back view of Radio Access Board 2
PHT/45184JD05/006	Front view of Digital Radio Board 1
PHT/45184JD05/007	Back view of Digital Radio Board 1
PHT/45184JD05/008	Front view of Digital Radio Board 2
PHT/45184JD05/009	Back view of Digital Radio Board 2
PHT/45184JD05/010	Front view of Duplex Filter 1
PHT/45184JD05/011	Back view of Duplex Filter 1
PHT/45184JD05/012	Front view of Duplex Filter 2
PHT/45184JD05/013	Back view of Duplex Filter 2
PHT/45184JD05/014	Front view of Heater
PHT/45184JD05/015	Back view of Heater
PHT/45184JD05/016	Top view of Power Supply Unit

RADIO FREQUENCY INVESTIGATION LTD.
Conformance Testing Department

TEST REPORT
Internal Photograph Section
S.No: RFI/MPTB2/RP45184JD05A

Test Of: Ericsson AB.
RBS 2308
To: FCC Part 22: 2002

Photographs of EUT (Continued)

Photo Reference Number	Title
PHT/45184JD05/017	Bottom view of Power Supply Unit
PHT/45184JD05/018	Internal view of Power Supply Unit
PHT/45184JD05/019	Front view of Power Interface Board
PHT/45184JD05/020	Back view of Power Interface Board
PHT/45184JD05/021	Top view of Y Interface Board
PHT/45184JD05/022	Bottom view of Y Interface Board
PHT/45184JD05/023	Top view of Radio Interface Board
PHT/45184JD05/024	Bottom view of Radio Interface Board
PHT/45184JD05/025	FCC ID Label

RADIO FREQUENCY INVESTIGATION LTD.

Conformance Testing Department

TEST REPORT

Internal Photograph Section

S.No: RFI/MPTB2/RP45184JD05A

Test Of: Ericsson AB.

RBS 2308

To: FCC Part 22: 2002

PHT/45184JD05/001 Open view of RRU-M EDGE.



RADIO FREQUENCY INVESTIGATION LTD.

Conformance Testing Department

TEST REPORT

Internal Photograph Section


S.No: RFI/MPTB2/RP45184JD05A

Test Of: Ericsson AB.

RBS 2308

To: FCC Part 22: 2002

PHT/45184JD05/002 Front view of Radio Access Board 1.



RADIO FREQUENCY INVESTIGATION LTD.

Conformance Testing Department

TEST REPORT

Internal Photograph Section


S.No: RFI/MPTB2/RP45184JD05A

Test Of: Ericsson AB.

RBS 2308

To: FCC Part 22: 2002

PHT/45184JD05/003 Back view of Radio Access Board 1.



RADIO FREQUENCY INVESTIGATION LTD.

Conformance Testing Department

TEST REPORT

Internal Photograph Section


S.No: RFI/MPTB2/RP45184JD05A

Test Of: Ericsson AB.

RBS 2308

To: FCC Part 22: 2002

PHT/45184JD05/004 Front view of Radio Access Board 2.



RADIO FREQUENCY INVESTIGATION LTD.

Conformance Testing Department

TEST REPORT

Internal Photograph Section


S.No: RFI/MPTB2/RP45184JD05A

Test Of: Ericsson AB.

RBS 2308

To: FCC Part 22: 2002

PHT/45184JD05/005 Back view of Radio Access Board 2.



RADIO FREQUENCY INVESTIGATION LTD.

Conformance Testing Department

TEST REPORT

Internal Photograph Section


S.No: RFI/MPTB2/RP45184JD05A

Test Of: Ericsson AB.

RBS 2308

To: FCC Part 22: 2002

PHT/45184JD05/006 Front view of Digital Radio Board 1.



RADIO FREQUENCY INVESTIGATION LTD.

Conformance Testing Department

TEST REPORT

Internal Photograph Section


S.No: RFI/MPTB2/RP45184JD05A

Test Of: Ericsson AB.

RBS 2308

To: FCC Part 22: 2002

PHT/45184JD05/007 Back view of Digital Radio Board 1.



RADIO FREQUENCY INVESTIGATION LTD.

Conformance Testing Department

TEST REPORT

Internal Photograph Section


S.No: RFI/MPTB2/RP45184JD05A

Test Of: Ericsson AB.

RBS 2308

To: FCC Part 22: 2002

PHT/45184JD05/008 Front view of Digital Radio Board 2.



RADIO FREQUENCY INVESTIGATION LTD.

Conformance Testing Department

TEST REPORT

Internal Photograph Section


S.No: RFI/MPTB2/RP45184JD05A

Test Of: Ericsson AB.

RBS 2308

To: FCC Part 22: 2002

PHT/45184JD05/009 Back view of Digital Radio Board 2.



RADIO FREQUENCY INVESTIGATION LTD.

Conformance Testing Department

TEST REPORT

Internal Photograph Section


S.No: RFI/MPTB2/RP45184JD05A

Test Of: Ericsson AB.

RBS 2308

To: FCC Part 22: 2002

PHT/45184JD05/010 Front view of Duplex Filter 1.



RADIO FREQUENCY INVESTIGATION LTD.

Conformance Testing Department

TEST REPORT

Internal Photograph Section


S.No: RFI/MPTB2/RP45184JD05A

Test Of: Ericsson AB.

RBS 2308

To: FCC Part 22: 2002

PHT/45184JD05/011 Back view of Duplex Filter 1.



RADIO FREQUENCY INVESTIGATION LTD.

Conformance Testing Department

TEST REPORT

Internal Photograph Section


S.No: RFI/MPTB2/RP45184JD05A

Test Of: Ericsson AB.

RBS 2308

To: FCC Part 22: 2002

PHT/45184JD05/012 Front view of Duplex Filter 2.



RADIO FREQUENCY INVESTIGATION LTD.

Conformance Testing Department

TEST REPORT

Internal Photograph Section


S.No: RFI/MPTB2/RP45184JD05A

Test Of: Ericsson AB.

RBS 2308

To: FCC Part 22: 2002

PHT/45184JD05/013 Back view of Duplex Filter 2.



RADIO FREQUENCY INVESTIGATION LTD.

Conformance Testing Department

TEST REPORT

Internal Photograph Section


S.No: RFI/MPTB2/RP45184JD05A

Test Of: Ericsson AB.

RBS 2308

To: FCC Part 22: 2002

PHT/45184JD05/014 Front view of Heater



RADIO FREQUENCY INVESTIGATION LTD.

Conformance Testing Department

TEST REPORT

Internal Photograph Section


S.No: RFI/MPTB2/RP45184JD05A

Test Of: Ericsson AB.

RBS 2308

To: FCC Part 22: 2002

PHT/45184JD05/015 Back view of Heater



RADIO FREQUENCY INVESTIGATION LTD.

Conformance Testing Department

TEST REPORT

Internal Photograph Section


S.No: RFI/MPTB2/RP45184JD05A

Test Of: Ericsson AB.

RBS 2308

To: FCC Part 22: 2002

PHT/45184JD05/016 Top view of Power Supply Unit



RADIO FREQUENCY INVESTIGATION LTD.

Conformance Testing Department

TEST REPORT

Internal Photograph Section

S.No: RFI/MPTB2/RP45184JD05A

Test Of: Ericsson AB.

RBS 2308

To: FCC Part 22: 2002

PHT/45184JD05/017 Bottom view of Power Supply Unit



RADIO FREQUENCY INVESTIGATION LTD.

Conformance Testing Department

TEST REPORT

Internal Photograph Section


S.No: RFI/MPTB2/RP45184JD05A

Test Of: Ericsson AB.

RBS 2308

To: FCC Part 22: 2002

PHT/45184JD05/018 Internal view of Power Supply Unit



RADIO FREQUENCY INVESTIGATION LTD.

Conformance Testing Department

TEST REPORT

Internal Photograph Section


S.No: RFI/MPTB2/RP45184JD05A

Test Of: Ericsson AB.

RBS 2308

To: FCC Part 22: 2002

PHT/45184JD05/019 Front view of Power Interface Board



RADIO FREQUENCY INVESTIGATION LTD.

Conformance Testing Department

TEST REPORT

Internal Photograph Section


S.No: RFI/MPTB2/RP45184JD05A

Test Of: Ericsson AB.

RBS 2308

To: FCC Part 22: 2002

PHT/45184JD05/020 Back view of Power Interface Board



RADIO FREQUENCY INVESTIGATION LTD.

Conformance Testing Department

TEST REPORT

Internal Photograph Section

S.No: RFI/MPTB2/RP45184JD05A

Test Of: Ericsson AB.

RBS 2308

To: FCC Part 22: 2002

PHT/45184JD05/021 Top view of Y Interface Board



RADIO FREQUENCY INVESTIGATION LTD.

Conformance Testing Department

TEST REPORT

Internal Photograph Section


S.No: RFI/MPTB2/RP45184JD05A

Test Of: Ericsson AB.

RBS 2308

To: FCC Part 22: 2002

PHT/45184JD05/022 Bottom view of Y Interface Board



RADIO FREQUENCY INVESTIGATION LTD.

Conformance Testing Department

TEST REPORT

Internal Photograph Section


S.No: RFI/MPTB2/RP45184JD05A

Test Of: Ericsson AB.

RBS 2308

To: FCC Part 22: 2002

PHT/45184JD05/023 Top view of Radio Interface Board



RADIO FREQUENCY INVESTIGATION LTD.

Conformance Testing Department

TEST REPORT

Internal Photograph Section


S.No: RFI/MPTB2/RP45184JD05A

Test Of: Ericsson AB.

RBS 2308

To: FCC Part 22: 2002

PHT/45184JD05/024 Bottom view of Radio Interface Board



RADIO FREQUENCY INVESTIGATION LTD.

Conformance Testing Department

TEST REPORT

Internal Photograph Section

S.No: RFI/MPTB2/RP45184JD05A

Test Of: Ericsson AB.

RBS 2308

To: FCC Part 22: 2002

PHT/45184JD05/025 FCC ID Label

