

May 15, 2001

Federal Comm Com
7435 Oakland Mills Rd
Columbia, MD 21036

Re: FCC ID:BFYM5016

Gentlemen:

In response to your email dated May 14, 2001 I have or will submit the following:

1. SAR test report in color. This consist of 2 files, Part 1 and Part 2. Splitting the file was necessary in order to reduce the file size to accommodate the limitations of the server system.
2. A reply to the issue of hands free operation has been received from the California agent for Shintom. Per the agent, the unit does not have an audio output jack and Shintom does not intend to produce a headset for this unit.

Phillip Inglis
TRP/Cetecom bvba
Agent for Shintom