



TEST REPORT No. R-TR78-FCC-TS-2

For

MODEL NO. 1657
FCC ID: C3K1657

Issue Date: May 15, 2015

FCC CFR47 Part 15 Subpart C

Prepared by
Microsoft EMC Laboratory
17760 NE 67th Ct,
Redmond WA, 98052, U.S.A.
425-421-9799
sajose@microsoft.com



1 Record of Revisions

This test report replaces Report #R-TR78-TS-1, previously issued by Microsoft EMC Labs on 04/13/2015.

2 Test Setup pictures



Fig.1 Radiated Spurious Emissions EUT Setup




Fig.2 Radiated Spurious Emissions Test Setup (30MHz – 1GHz)



Fig.3 Radiated Spurious Emissions Test Setup (1-18 GHz)



Fig.4 Radiated Spurious Emissions (18-26.5GHz)



Fig.5 Antenna port Conducted Measurements Test Setup




Fig.6 AC Line Conducted Emissions Measurements Test Setup



Fig.7 AC Line Conducted Emissions Measurements Test Setup