



**Intermec
Technologies
Corporation**

6001 36th Avenue West
Everett, Washington 98203
United States
tel 425.348.2600
fax 425.355.9551
www.intermec.com

17-NOVEMBER-2008

Federal Communications Commission
Authorization and Evaluation Division
7435 Oakland Mills Road
Columbia, Maryland 21046

Subject: Class II Permissive Change FCC ID: EHAIM4

Dear Application Examiner:

Intermec Technologies Corporation is submitting an application for a Class 2 Permissive Change for the model IM4 RFID radio, FCC ID: EHAIM4. Authorization of a new RF exposure condition is requested.

The IM4 radio is co-located with the model BTM4 Bluetooth radio, FCC ID: EHA-BTM4 in the Intermec Model IP30 RFID reader. This collocation configuration has been previously authorized.

The new RF exposure condition occurs when the Intermec CK3 Series handheld computer is connected to the IP30. The CK3 contains the model DDIB radio module, FCC ID: EHA-CK3DDIB. In this configuration, only hand-held use is possible, so MPE estimates were performed for the co-located radios. No changes have been made to the hardware or software of the radios in these co-located configurations.

Your efforts in reviewing this application are greatly appreciated.

Please contact me by telephone at (425) 356-1765 or by e-mail (sean.mackellar@Intermec.com) if there are questions or additional information needed concerning this request.

Sincerely,

A handwritten signature in blue ink, appearing to read "Sean MacKellar", is located below the "Sincerely," text.

**Sean MacKellar
Compliance Engineer
Intermec Technologies Corporation
6001 36th Avenue West
Everett, WA 98203-1264
425-356-1765**