

From: wendy@adt.com.tw [mailto:wendy@adt.com.tw]  
Sent: Tuesday, June 27, 2006 10:21 PM  
To: steve.cheng  
Subject: Re : TCB Review Comments for (A06-0627a- FDI-04600264-0- Buffalo  
11grouterClass II)

Dear Steve

Pls see our reply as below:

TCB Review Comments for (A06-0627a- FDI-04600264-0- Buffalo 11g router  
Class II)

-EMC-

Question #1: P6 of test report mentioned that new Turbo Mode is added to the product, but there is no related test data in the report to address this new mode. Please supply.

(Embedded image moved to file: pic27446.gif)

ANS: Difference between normal mode and turbo mode is only software compression technology, modulation type and bandwidth is the same, so we evaluate worst data rate in 11g include normal and turbo mode.

Thanks for your assistance!

Best Regards  
Wendy Liao

Wendy Liao (廖意紋)/ ADT Corp.  
TEL: 03-318-3232 EXT 1625  
FAX: 03-318-5050  
Email: wendy@adt.com.tw  
地址:桃園縣龜山鄉文化村華亞二路 1 9 號