

FCC TEST REPORT

APPENDIX B. Photographs of EUT

Model No. HT580S

772003




772003



FCC TEST REPORT


772003



772003



FCC TEST REPORT




FCC TEST REPORT



772003



772003




FCC TEST REPORT




FCC TEST REPORT

772003




772003




FCC TEST REPORT



772003



772003




FCC TEST REPORT




FCC TEST REPORT

772003




772003




FCC TEST REPORT


772003





772003



FCC TEST REPORT




FCC TEST REPORT



772003




772003




FCC TEST REPORT

772003




772003



FCC TEST REPORT

772003



772003



FCC TEST REPORT

APPENDIX B. Photographs of EUT

Model No. HT580

772003




772003



FCC TEST REPORT


772003



772003



FCC TEST REPORT




FCC TEST REPORT

772003




772003




FCC TEST REPORT



772003




772003



FCC TEST REPORT




FCC TEST REPORT




FCC TEST REPORT

772003




772003






FCC TEST REPORT

772003



772003





FCC TEST REPORT


772003



772003





FCC TEST REPORT



FCC TEST REPORT



FCC TEST REPORT




FCC TEST REPORT

772003



772003



FCC TEST REPORT

