



MOTOROLA

Date: April 22, 2008

Subject: Request for additional information regarding FCC ID: IHDP56HU1

Reference:

Correspondence Reference Number: IHD80241
Confirmation Number: 803260241-43
Date of Original Email: April 18, 2008

Prepared by:

Andrew Bachler, Principal Staff Engineer
Motorola Mobile Device Business
Libertyville, Illinois 60048

Questions and responses follow:

1. Please include Bluetooth Block Diagram including clock/oscillator values.

Response: Please refer to the revised Exhibit 4 attached, the Bluetooth block diagram with clock/oscillator values is shown on page 2 of the exhibit.

2. Thermotron S-4 Chamber in Exhibit 6 shows calibration may have been out of cal for the tests. Please address.

Response: Please refer to the revised Exhibit 6 which reflects the correction of the typo on the date.

3. Page 81 of the Users Manual describe ICNIRP limits but shows SAR values supposed to be compared against IEEE limits. Please revise/update.

Response: Please refer to the revised User Manual with SAR values compared against to FCC SAR limits.