


Registration number: W6R20809-9335

FCC ID: IIOCWR-635M


## Internal Photos






Registration number: W6R20809-9335

FCC ID: IIOCWR-635M






Registration number: W6R20809-9335

FCC ID: IIOCWR-635M







# **Worldwide Testing Services(Taiwan) Co., Ltd.**

Registration number: W6R20809-9335

FCC ID: II0CWR-635M







# **Worldwide Testing Services(Taiwan) Co., Ltd.**

Registration number: W6R20809-9335


FCC ID: IIOCWR-635M






Registration number: W6R20809-9335


FCC ID: IIOCWR-635M






Registration number: W6R20809-9335

FCC ID: IIOCWR-635M






## Worldwide Testing Services(Taiwan) Co., Ltd.

Registration number: W6R20809-9335

FCC ID: IIOCWR-635M





Registration number: W6R20809-9335

FCC ID: IIOCWR-635M



Registration number: W6R20809-9335

FCC ID: IIOCWR-635M

