FCC TEST REPORT Report No.: F352805

1.1. Photographs of Conducted Emission Test Configuration

■ The photographs show the configuration that generates the maximum emission.




FRONT VIEW



REAR VIEW

SPORTON International Inc. TEL: 886-2-2696-2468 FAX: 886-2-2696-2255

FCC ID : IOU9210S01 Page No. : 1 of 3 Issued Date : Jul. 04, 2003 FCC TEST REPORT Report No.: F352805



SIDE VIEW

 SPORTON International Inc.
 FCC ID
 : IOU9210S01


 TEL: 886-2-2696-2468
 Page No.
 : 2 of 3

 FAX: 886-2-2696-2255
 Issued Date
 : Jul. 04, 2003


FCC TEST REPORT Report No.: F352805

1.2. Photographs of Radiated Emission Test Configuration

■ The photographs show the configuration that generates the maximum emission.



FRONT VIEW



REAR VIEW

SPORTON International Inc. TEL: 886-2-2696-2468 FAX: 886-2-2696-2255

FCC ID : IOU9210S01 Page No. : 3 of 3 Issued Date : Jul. 04, 2003