



Internal photographs of GMR 40X.
Modulator Top and Bottom





ROGERS LABS, INC.
4405 W. 259th Terrace
Louisburg, KS 66053
Phone/Fax: (913) 837-3214



Garmin International, Inc.
MODEL: GMR40X
Test #: 060406
Test to: FCC Parts 2 and 80

IC: 1792A-00991
FCCID#: IPH-00991
Page 1 of 9

IF Board 1 Top and Bottom



IF Board 2 Top and Bottom





ROGERS LABS, INC.
4405 W. 259th Terrace
Louisburg, KS 66053
Phone/Fax: (913) 837-3214

Garmin International, Inc.
MODEL: GMR40X
Test #: 060406
Test to: FCC Parts 2 and 80

IC: 1792A-00991
FCCID#: IPH-00991
Page 3 of 9



Rotation detector top and bottom



ROGERS LABS, INC. Garmin International, Inc.
4405 W. 259th Terrace MODEL: GMR40X
Louisburg, KS 66053 Test #: 060406
Phone/Fax: (913) 837-3214 Test to: FCC Parts 2 and 80

IC: 1792A-00991
FCCID#: IPH-00991
Page 4 of 9

Main Board top and bottom




ROGERS LABS, INC.
4405 W. 259th Terrace
Louisburg, KS 66053
Phone/Fax: (913) 837-3214



Garmin International, Inc.
MODEL: GMR40X
Test #: 060406
Test to: FCC Parts 2 and 80

IC: 1792A-00991
FCCID#: IPH-00991
Page 5 of 9

Voltage Converter top and bottom





Down Converter top and bottom





ROGERS LABS, INC. Garmin International, Inc.
4405 W. 259th Terrace MODEL: GMR40X
Louisburg, KS 66053 Test #: 060406
Phone/Fax: (913) 837-3214 Test to: FCC Parts 2 and 80

IC: 1792A-00991
FCCID#: IPH-00991
Page 7 of 9

Voltage converter top and bottom



Motor control top and bottom



ROGERS LABS, INC.
4405 W. 259th Terrace
Louisburg, KS 66053
Phone/Fax: (913) 837-3214

Garmin International, Inc.
MODEL: GMR40X
Test #: 060406
Test to: FCC Parts 2 and 80

IC: 1792A-00991
FCCID#: IPH-00991
Page 9 of 9