



ROGERS LABS, INC.

4405 West 259th Terrace
Louisburg, KS 66053
Phone / Fax (913) 837-3214

November 4, 2010

Timco Engineering Inc.
849 NW State Road 45
Newberry, FL 32669

Applicant: Garmin International, Inc. Equipment: FCC ID: IPH-0140000
 1200 East 151st Street CORES number: 0005-0885-88
 Olathe, KS 66062

FCC Rules: Parts 2 and 87

Men

Please find exhibits uploaded for use in replacing exhibits and correction for the grant of certification (FCC ID: IPH-0140000).

Garmin desires the removal of the RF compliance statements currently placed on the grant of certification. There is precedence for this as defined in CFR47 for aviation transceivers.

Garmin states the Grant note should read as follows

“Power output is conducted and measured at the antenna terminal. This device contains functions that are not operational in U.S. Territories. This filing is only applicable for U.S. operation.”

This removes the second through fourth sentences in the current grant note.

In addition, type errors have been discovered and corrected in test report originally submitted. Please replace originally submitted documentation for these exhibits with the revised files uploaded with this request.

- 1) Test report exhibit – file: GIA63w TstRpt 100929 r3.pdf to replace original test report exhibit (type errors and model reference addition of GIA 63H)
- 2) Add this cover letter if required requesting these corrections

Should you require any further information, please contact the undersigned.
Thank you for your consideration in this matter.

Sincerely,

Scot Rogers
Rogers Labs, Inc.
Enclosures