

Test setup photographs



R Rogers Labs, Inc.  
4405 West 259<sup>th</sup> Terrace  
Louisburg, KS 66053  
Phone/Fax: (913) 837-3214  
Revision 1

Garmin International, Inc.  
Model: 011-02139-xx      GPN: 011-02139-xx  
Test #: 090428              SN: 1NQ000031  
Test to: CFR47 Parts 2 and 15.249, RSS-210  
File: TSup 01554


FCC ID#: IPH-01554  
IC: 1792A-01554  
Page 1 of 3  
Date: May 6, 2009



R Rogers Labs, Inc.  
4405 West 259<sup>th</sup> Terrace  
Louisburg, KS 66053  
Phone/Fax: (913) 837-3214  
Revision 1

Garmin International, Inc.  
Model: 011-02139-xx      GPN: 011-02139-xx  
Test #: 090428              SN: 1NQ000031  
Test to: CFR47 Parts 2 and 15.249, RSS-210  
File: TSup 01554

FCC ID#: IPH-01554  
IC: 1792A-01554  
Page 2 of 3  
Date: May 6, 2009



R Rogers Labs, Inc.  
4405 West 259<sup>th</sup> Terrace  
Louisburg, KS 66053  
Phone/Fax: (913) 837-3214  
Revision 1

Garmin International, Inc.  
Model: 011-02139-xx      GPN: 011-02139-xx  
Test #: 090428              SN: 1NQ000031  
Test to: CFR47 Parts 2 and 15.249, RSS-210  
File: TSup 01554

FCC ID#: IPH-01554  
IC: 1792A-01554  
Page 3 of 3  
Date: May 6, 2009