



Test setup photographs



Rogers Labs, Inc.
4405 West 259th Terrace
Louisburg, KS 66053
Phone/Fax: (913) 837-3214
Revision 1

Garmin International, Inc.
Models: GPSMAP 62Sc, GPSMAP 62Stc
Test #: 110515 SN: ENGI
Test to: FCC Parts 2 and 15.249, RSS-210
File: TSUP 02416

FCC ID: IPH-02416
IC: 1792A-02416
GPN: 011-02416-2x
Date: May 31, 2011
Page 1 of 3



Rogers Labs, Inc.
4405 West 259th Terrace
Louisburg, KS 66053
Phone/Fax: (913) 837-3214
Revision 1

Garmin International, Inc.
Models: GPSMAP 62Sc, GPSMAP 62Stc
Test #:110515 SN: ENGI
Test to: FCC Parts 2 and 15.249, RSS-210
File: TSup 02416

FCC ID: IPH-02416
IC: 1792A-02416
GPN: 011-02416-2x
Date: May 31, 2011
Page 2 of 3



Rogers Labs, Inc.
4405 West 259th Terrace
Louisburg, KS 66053
Phone/Fax: (913) 837-3214
Revision 1

Garmin International, Inc.
Models: GPSMAP 62Sc, GPSMAP 62Stc
Test #:110515 SN: ENGI
Test to: FCC Parts 2 and 15.249, RSS-210
File: TSup 02416

FCC ID: IPH-02416
IC: 1792A-02416
GPN: 011-02416-2x
Date: May 31, 2011
Page 3 of 3