



Top side PCB with Shielding



Top side PCB Shielding removed




Rogers Labs, Inc.  
4405 West 259<sup>th</sup> Terrace  
Louisburg, KS 66053  
Phone/Fax: (913) 837-3214  
Revision 1

Garmin International, Inc.  
Model: A03680  
Test: 190909  
Test to: CFR47 15C, RSS-Gen, RSS-210  
File: A03680 Short Term Conf IntPho

SN's: 3301523216, 33001523028  
FCC ID: IPH-03680  
IC: 1792A-03680  
Date: November 8, 2019  
Page 1 of 4

Inside Case




Bottom side PCB



Rogers Labs, Inc.  
4405 West 259<sup>th</sup> Terrace  
Louisburg, KS 66053  
Phone/Fax: (913) 837-3214  
Revision 1

Garmin International, Inc.  
Model: A03680  
Test: 190909  
Test to: CFR47 15C, RSS-Gen, RSS-210  
File: A03680 Short Term Conf IntPho


SN's: 3301523216, 33001523028  
FCC ID: IPH-03680  
IC: 1792A-03680  
Date: November 8, 2019  
Page 2 of 4



Rogers Labs, Inc.  
4405 West 259<sup>th</sup> Terrace  
Louisburg, KS 66053  
Phone/Fax: (913) 837-3214  
Revision 1

Garmin International, Inc.  
Model: A03680  
Test: 190909  
Test to: CFR47 15C, RSS-Gen, RSS-210  
File: A03680 Short Term Conf IntPho

SN's: 3301523216, 33001523028  
FCC ID: IPH-03680  
IC: 1792A-03680  
Date: November 8, 2019  
Page 3 of 4



Rogers Labs, Inc.  
4405 West 259<sup>th</sup> Terrace  
Louisburg, KS 66053  
Phone/Fax: (913) 837-3214  
Revision 1

Garmin International, Inc.  
Model: A03680  
Test: 190909  
Test to: CFR47 15C, RSS-Gen, RSS-210  
File: A03680 Short Term Conf IntPho

SN's: 3301523216, 33001523028  
FCC ID: IPH-03680  
IC: 1792A-03680  
Date: November 8, 2019  
Page 4 of 4