


Top side of PCB inside enclosure




Rogers Labs, Inc.  
4405 West 259<sup>th</sup> Terrace  
Louisburg, KS 66053  
Phone/Fax: (913) 837-3214  
Revision 1

Garmin International, Inc.  
Model: 03754  
Test: 190318  
Test to: CFR47 15C, RSS-Gen RSS-247  
File: 03754 Short Term Conf IntPho

SN's: 3986442368 / 3986442344  
FCC ID: IPH-03754  
IC: 1792A-03754  
Date: March 3, 2020  
Page 1 of 5

Top side with antenna




Rogers Labs, Inc.  
4405 West 259<sup>th</sup> Terrace  
Louisburg, KS 66053  
Phone/Fax: (913) 837-3214  
Revision 1

Garmin International, Inc.  
Model: 03754  
Test: 190318  
Test to: CFR47 15C, RSS-Gen RSS-247  
File: 03754 Short Term Conf IntPho

SN's: 3986442368 / 3986442344  
FCC ID: IPH-03754  
IC: 1792A-03754  
Date: March 3, 2020  
Page 2 of 5

Board PCB




Rogers Labs, Inc.  
4405 West 259<sup>th</sup> Terrace  
Louisburg, KS 66053  
Phone/Fax: (913) 837-3214  
Revision 1

Garmin International, Inc.  
Model: 03754  
Test: 190318  
Test to: CFR47 15C, RSS-Gen RSS-247  
File: 03754 Short Term Conf IntPho

SN's: 3986442368 / 3986442344  
FCC ID: IPH-03754  
IC: 1792A-03754  
Date: March 3, 2020  
Page 3 of 5

Antenna and IC



Rogers Labs, Inc.  
4405 West 259<sup>th</sup> Terrace  
Louisburg, KS 66053  
Phone/Fax: (913) 837-3214  
Revision 1

Garmin International, Inc.  
Model: 03754  
Test: 190318  
Test to: CFR47 15C, RSS-Gen RSS-247  
File: 03754 Short Term Conf IntPho

SN's: 3986442368 / 3986442344  
FCC ID: IPH-03754  
IC: 1792A-03754  
Date: March 3, 2020  
Page 4 of 5

Inside bottom of enclosure



Rogers Labs, Inc.  
4405 West 259<sup>th</sup> Terrace  
Louisburg, KS 66053  
Phone/Fax: (913) 837-3214  
Revision 1

Garmin International, Inc.  
Model: 03754  
Test: 190318  
Test to: CFR47 15C, RSS-Gen RSS-247  
File: 03754 Short Term Conf IntPho

SN's: 3986442368 / 3986442344  
FCC ID: IPH-03754  
IC: 1792A-03754  
Date: March 3, 2020  
Page 5 of 5