



Test setup photographs



Rogers Labs, Inc.  
4405 West 259<sup>th</sup> Terrace  
Louisburg, KS 66053  
Phone/Fax: (913) 837-3214  
Revision 1

Garmin International, Inc.  
Models: A03873, B03873  
Test: 200713\_14 SN's: 3336556891, 3333597072, 3336556773  
Test to: CFR47 15.C, RSS-210, RSS-247  
File: 03873 TSup

FCC ID: IPH-03873  
IC: 1792A-03873  
Date: October 20, 2020  
Page 1 of 3



Rogers Labs, Inc.  
4405 West 259<sup>th</sup> Terrace  
Louisburg, KS 66053  
Phone/Fax: (913) 837-3214  
Revision 1

Garmin International, Inc.  
Models: A03873, B03873  
Test: 200713\_14 SN's: 3336556891, 3333597072, 3336556773  
Test to: CFR47 15.C, RSS-210, RSS-247  
File: 03873 TSup

FCC ID: IPH-03873  
IC: 1792A-03873  
Date: October 20, 2020  
Page 2 of 3



Rogers Labs, Inc.  
4405 West 259<sup>th</sup> Terrace  
Louisburg, KS 66053  
Phone/Fax: (913) 837-3214  
Revision 1

Garmin International, Inc.  
Models: A03873, B03873  
Test: 200713\_14 SN's: 3336556891, 3333597072, 3336556773  
Test to: CFR47 15.C, RSS-210, RSS-247  
File: 03873 TSup

FCC ID: IPH-03873  
IC: 1792A-03873  
Date: October 20, 2020  
Page 3 of 3