

Internal photographs of equipment under test  
Inside enclosure




Rogers Labs, Inc.  
4405 West 259<sup>th</sup> Terrace  
Louisburg, KS 66053  
Phone/Fax: (913) 837-3214  
Revision 1

Garmin International, Inc.  
Model: A04158  
Test: 210307  
Test to: CFR47 15C, RSS-210, RSS-247  
File: A04158 Short Term Conf IntPho

SN's: 3354564362 / 3354564378  
FCC ID: IPH-04158  
IC: 1792A-04158  
Date: June 21, 2021  
Page 1 of 5

Back Side without Shield




Rogers Labs, Inc.  
4405 West 259<sup>th</sup> Terrace  
Louisburg, KS 66053  
Phone/Fax: (913) 837-3214  
Revision 1

Garmin International, Inc.  
Model: A04158  
Test: 210307  
Test to: CFR47 15C, RSS-210, RSS-247  
File: A04158 Short Term Conf IntPho

SN's: 3354564362 / 3354564378  
FCC ID: IPH-04158  
IC: 1792A-04158  
Date: June 21, 2021  
Page 2 of 5

Back Side with Shield and 2.4 GHz Antenna



Rogers Labs, Inc.  
4405 West 259<sup>th</sup> Terrace  
Louisburg, KS 66053  
Phone/Fax: (913) 837-3214  
Revision 1

Garmin International, Inc.  
Model: A04158  
Test: 210307  
Test to: CFR47 15C, RSS-210, RSS-247  
File: A04158 Short Term Conf IntPho

SN's: 3354564362 / 3354564378  
FCC ID: IPH-04158  
IC: 1792A-04158  
Date: June 21, 2021  
Page 3 of 5



