


**EXHIBIT 15 – PHOTOS – EMC AND SAR SETUP**


**Figure E15.1 – Setup, Conducted Measurements**




**Figure E15.2 – Setup, Radiated Measurements, 9kHz – 30MHz**



**Figure E15.3 – Setup, Radiated Measurements, 30 – 1000MHz**



**Figure E15.4 – Setup, Radiated Rx Measurements, 1 – 18GHz**




**Figure E15.5 – Setup, Radiated Tx Measurements, 1 – 18GHz**



**Figure E15.6 – Setup, Radiated Tx Measurements, 18 – 26GHz**



**Figure E15.7 – Setup, Frequency Stability**




**Figure E15.8 – Setup, Frequency Stability**




**Figure E15.9 – Setup, Line Conducted Measurements**




**Figure 15.10 SAR Setup: Extremity, DUT Back 0mm- Silicone Band**



**15.11 SAR Setup: Extremity, DUT Back 0mm- Silicone Band - close**



**15.12 SAR Setup: Face, DUT Front 10mm – Silicone Band**



**15.13 SAR Setup: Face, DUT Front 10mm – Silicone Band – close**

