



Test setup photographs



Rogers Labs, Inc.  
4405 West 259<sup>th</sup> Terrace  
Louisburg, KS 66053  
Phone/Fax: (913) 837-3214  
Revision 1

Garmin International, Inc.  
Model: AA2557  
Test #: 1512151  
Test to: CFR47 15C, RSS-247  
File: AA2557 TSup


SN: 4MQ000062  
FCC ID: IPH-A2557  
IC: 1792A-A2557  
Date: January 26, 2016  
Page 1 of 4



Rogers Labs, Inc.  
4405 West 259<sup>th</sup> Terrace  
Louisburg, KS 66053  
Phone/Fax: (913) 837-3214  
Revision 1

Garmin International, Inc.  
Model: AA2557  
Test #: 1512151  
Test to: CFR47 15C, RSS-247  
File: AA2557 TSUp

SN: 4MQ000062  
FCC ID: IPH-A2557  
IC: 1792A-A2557  
Date: January 26, 2016  
Page 2 of 4



Rogers Labs, Inc.  
4405 West 259<sup>th</sup> Terrace  
Louisburg, KS 66053  
Phone/Fax: (913) 837-3214  
Revision 1

Garmin International, Inc.  
Model: AA2557  
Test #: 1512151  
Test to: CFR47 15C, RSS-247  
File: AA2557 TSUp

SN: 4MQ000062  
FCC ID: IPH-A2557  
IC: 1792A-A2557  
Date: January 26, 2016  
Page 3 of 4



Rogers Labs, Inc.  
4405 West 259<sup>th</sup> Terrace  
Louisburg, KS 66053  
Phone/Fax: (913) 837-3214  
Revision 1

Garmin International, Inc.  
Model: AA2557  
Test #: 1512151  
Test to: CFR47 15C, RSS-247  
File: AA2557 TSup

SN: 4MQ000062  
FCC ID: IPH-A2557  
IC: 1792A-A2557  
Date: January 26, 2016  
Page 4 of 4