


Internal Photographs



GPA65 Internal photograph of the Transmitter board



GTS8XX Internal photograph of the Transmitter board


Rogers Labs, Inc.
4405 W. 259th Terrace
Louisburg, KS 66053
Phone/Fax: (913) 837-3214
Revision 1

Garmin International, Inc.
Model: GTS 850
Test #: 090619A
Test to: FCC Parts 2, and 87
File: IntPho IPH0104450

SN: 1EB000014
FCC ID#: IPH0104450
Page 1 of 5
Date: 7/15/2009




GTS8XX Internal photograph of the Power Supply board (top side)



GTS8XX Internal photograph of the Power Supply board (bottom side)



GTS8XX Internal photograph of the Receiver board



GPA65 Internal photograph of the Receiver board


Rogers Labs, Inc.
4405 W. 259th Terrace
Louisburg, KS 66053
Phone/Fax: (913) 837-3214
Revision 1

Garmin International, Inc.
Model: GTS 850
Test #: 090619A
Test to: FCC Parts 2, and 87
File: IntPho IPH0104450


SN: 1EB000014
FCC ID#: IPH0104450
Page 3 of 5
Date: 7/15/2009



GTS8XX External photograph of RF cables within the chassis



GTS8XX Internal photograph of Qtr Wave Stub Board (top side)



GTS8XX Internal photograph of Qtr Wave Stub Board (bottom side)