



Internal Photographs

Internal photograph of the Main Transmitter board Front



Internal photograph of the Main Transmitter board Back




Rogers Labs, Inc.
4405 West 259th Terrace
Louisburg, KS 66053
Phone/Fax: (913) 837-3214
Revision 1


Garmin International, Inc.
Model: GTS Processor SN: 28P000318
Test #: 111109
Test to: CFR47 Parts 2 and 87
File: Short Term Conf IntPho IPH0104455

GPN: 011-02571-00
FCC ID: IPH0104455
Date: December 15, 2011
Date: 12/15/2011

Internal photograph of the Power Supply Transmitter board Front



Internal photograph of the Power Supply Transmitter board Back




Rogers Labs, Inc.
4405 West 259th Terrace
Louisburg, KS 66053
Phone/Fax: (913) 837-3214
Revision 1


Garmin International, Inc.
Model: GTS Processor SN: 28P000318
Test #: 111109
Test to: CFR47 Parts 2 and 87
File: Short Term Conf IntPho IPH0104455

GPN: 011-02571-00
FCC ID: IPH0104455
Date: December 15, 2011
Date: 12/15/2011

Internal photograph of the High Power Transmitter board Front



Internal photograph of the High Power Transmitter board Back



Rogers Labs, Inc.
4405 West 259th Terrace
Louisburg, KS 66053
Phone/Fax: (913) 837-3214
Revision 1


Garmin International, Inc.
Model: GTS Processor SN: 28P000318
Test #: 111109
Test to: CFR47 Parts 2 and 87
File: Short Term Conf IntPho IPH0104455

GPN: 011-02571-00
FCC ID: IPH0104455
Date: December 15, 2011
Date: 12/15/2011

Internal photograph of the Boost Supply Transmitter board Front



Internal photograph of the Boost Supply Transmitter board Back



Rogers Labs, Inc.
4405 West 259th Terrace
Louisburg, KS 66053
Phone/Fax: (913) 837-3214
Revision 1

Garmin International, Inc.
Model: GTS Processor SN: 28P000318
Test #: 111109
Test to: CFR47 Parts 2 and 87
File: Short Term Conf IntPho IPH0104455

GPN: 011-02571-00
FCC ID: IPH0104455
Date: December 15, 2011
Date: 12/15/2011