



Intertek Testing Services

ETL SEMKO

Report No.: 03084241
Talk (4 Handsets) Mode

Tested By: Hong, Report No.: 03084241

Scan Settings (1 Range)

Frequencies			Receiver Settings					
Start	Stop	Step	IF BW	Detector	M-Time	Atten	Preamp	OpRge
150k	30M	5k	10k	PK+AV	10ms	AUTO	LN OFF	60dB


Final Measurement: x QP / + AV

Meas Time: 1 s

Subranges: 16

Acc Margin: 20dB

Transducer No.	Start	Stop	Name
21	9k	30M	EW0698



Ctrl No.: N/A



Intertek Testing Services

ETL SEMKO

Report No.: 03084241
Talk (4 Handsets) Mode

Tested By: Hong, Report No.: 03084241

Scan Settings (1 Range)

|----- Frequencies -----||----- Receiver Settings -----|

Start	Stop	Step	IF BW	Detector	M-Time	Atten	Preamp	OpRge
150k	30M	5k	10k	PK+AV	10ms	AUTO	LN OFF	60dB

Final Measurement

Frequency QP Level QP Limit

MHz	dBuV	dBuV
-----	------	------

0.37000	33.2	58.5
---------	------	------

0.47500	33.6	56.4
---------	------	------

0.71500	27.1	56.0
---------	------	------

Frequency AV Level AV Limit

MHz	dBuV	dBuV
-----	------	------

no Results

* limit



Intertek Testing Services

ETL SEMKO

Report No.: 03084242
Charging Mode with
Additional Charger

Tested By: Hong, Report No.: 03084242

Scan Settings (1 Range)

|----- Frequencies -----||----- Receiver Settings -----|

Start	Stop	Step	IF BW	Detector	M-Time	Atten	Preamp	OpRge
150k	30M	5k	10k	PK+AV	10ms	AUTO	LN OFF	60dB

Final Measurement: x QP / + AV


Meas Time: 1 s

Subranges: 16

Acc Margin: 20dB

Transducer No. Start Stop Name

21 9k 30M EW0698



PAGE 1

Ctrl No.: N/A



Intertek Testing Services

ETL SEMKO

Report No.: 03084242
Charging Mode with
Additional Charger

Tested By: Hong, Report No.: 03084242

Scan Settings (1 Range)

|----- Frequencies -----||----- Receiver Settings -----|

Start	Stop	Step	IF BW	Detector	M-Time	Atten	Preamp	OpRge
150k	30M	5k	10k	PK+AV	10ms	AUTO	LN OFF	60dB

Final Measurement

no Results

Ctrl No.: N/A