




Cisco Systems, Inc.
170 West Tasman Drive
San Jose, CA 95134-1706
Phone 408 526-4000
Fax: 408 526 -4100
<http://www.cisco.com>

Exhibit : Internal Photos


Model: 73-15453-03
FCC ID: LDKAGORA0916
IC ID: 2461B-AGORA0916

Internal – PCB mains board of ASR901 router (Top View)




The 73-15453-03 radio module plugs into the mini PCIe slot of the ASR901 router main board here.

Internal- PCB mains board of ASR901 router (Bottom)



ASR901 Antenna cable connection



The 73-15453-03 radio module plugs into the antenna cable of the ASR901 router main board here.

