

Description of Changes
on
FZV Receiver, FCC ID LX8FZVE
of
Bayerische Motoren Werke AG

The following modifications have been made:

1. The receiver circuit was moved from a separate cabinet into the windshield mirror.
2. The antenna was changed from coupling to heating wires to a piece of wire in the mirror cabinet.

