



ANNEX C: INTERNAL PHOTOGRAPHS




143563_f.JPG: RLS, internal view 1 (cover removed)

ANNEX C: INTERNAL PHOTOGRAPHS




143563_h.JPG: RLS, internal view 2 (absorbing material for TX patch)

ANNEX C: INTERNAL PHOTOGRAPHS




143563_i.JPG: RLS, PCB, top view

ANNEX C: INTERNAL PHOTOGRAPHS




143563_n.JPG: RLS, PCB, top view (shielding cover removed)

ANNEX C: INTERNAL PHOTOGRAPHS




143563_j.JPG: RLS, PCB, bottom view

ANNEX C: INTERNAL PHOTOGRAPHS




143563_m.JPG: RLS, PCB, bottom view (shielding cover removed)

ANNEX C: INTERNAL PHOTOGRAPHS



143563_k.JPG: RLS, detail view to TX patch and shielding cover

ANNEX C: INTERNAL PHOTOGRAPHS



143563_I.JPG: RLS, detail view to RX patch and shielding cover