## Tune Up Procedure

## 1. OBAPA1060

-AFTER PRESSING THE PTT AND CHECK THE TX POWER AT THE CH. 1, ADJUST R505 OR C501 TO MEET 0.228W