




Figure 337: Spurious Emissions at Antenna Terminal 64QAM, 1932.5MHz,
B.W. 5MHz, Sub Carrier 15 kHz




Figure 338: Spurious Emissions at Antenna Terminal 64QAM, 1962.5MHz,
B.W. 5MHz, Sub Carrier 15 kHz




Figure 339: Spurious Emissions at Antenna Terminal 64QAM, 1992.5MHz,
B.W. 5MHz, Sub Carrier 15 kHz




Figure 340: Spurious Emissions at Antenna Terminal 64QAM, 1932.5MHz,
B.W. 5MHz, Sub Carrier 30 kHz




Figure 341: Spurious Emissions at Antenna Terminal 64QAM, 1962.5MHz,
B.W. 5MHz, Sub Carrier 30 kHz




Figure 342: Spurious Emissions at Antenna Terminal 64QAM, 1992.5MHz,
B.W. 5MHz, Sub Carrier 30 kHz




Figure 343: Spurious Emissions at Antenna Terminal 64QAM, 1935.0MHz,
B.W. 10MHz, Sub Carrier 15 kHz




Figure 344: Spurious Emissions at Antenna Terminal 64QAM, 1962.5MHz,
B.W. 10MHz, Sub Carrier 15 kHz




Figure 345: Spurious Emissions at Antenna Terminal 64QAM, 1990.0MHz,
B.W. 10MHz, Sub Carrier 15 kHz




Figure 346: Spurious Emissions at Antenna Terminal 64QAM, 1935.0MHz,
B.W. 10MHz, Sub Carrier 30 kHz




Figure 347: Spurious Emissions at Antenna Terminal 64QAM, 1962.5MHz,
B.W. 10MHz, Sub Carrier 30 kHz




Figure 348: Spurious Emissions at Antenna Terminal 64QAM, 1990.0MHz,
B.W. 10MHz, Sub Carrier 30 kHz