






360 Herndon Parkway
Suite 1400
Herndon, VA 20170
<http://www.rheintech.com>


25 INTERNAL PHOTOGRAPHS





Gland Housing Lid Inside




Outdoor Unit without Front Cover




Outdoor Unit with no Baseband Processor Assembly




Baseband Processor Assembly with Cans





Baseband Processor PCB Top without Cans




Baseband Processor PCB Bottom with can




Baseband Processor PCB Bottom without can




Baseband Processor Assembly Side-on




PSU/TCXO PSU Top with Can





PSU/TCXO PSU Top without Can





PSU/TCXO PSU Bottom with Can





PSU/TCXO PSU Bottom without Can





Tx Housing Assembly Closed





Tx Housing Assembly Open





Tx Housing Assembly Bottom





Rx Housing Assembly Closed




Rx Housing Assembly Open




Rx Housing Assembly Bottom




Power Amplifier Closed



1




Power Amplifier Open



External Cable Interface PCB



External Cable Interface and Lightning Protection Assembly



Indoor Unit Inside

Indoor Unit Component Side



Indoor Unit Solder Side

