

ZIPPY TECHNOLOGY CORP. , FCC ID: P4PBT310, Assessment NO.: AN07T6468, Notice#1 [Inbox](#)

☆ from "tim.dwyer@ccsemc.com" <tim.dwyer@ccsemc.com> [hide details](#) Jan 23 [Reply](#) | [▼](#)
to application@tw.ccsemc.com
cc tim.dwyer@ccsemc.com
date Jan 23, 2007 8:01 PM
subject ZIPPY TECHNOLOGY CORP. , FCC ID: P4PBT310, Assessment NO.: AN07T6468, Notice#1

Dear CCS TW,

The review of this application is complete. Please reply to the following items:

1. Please provide a revised schematic showing the antenna and any circuitry associated with the antenna.
2. The user manual refers to the use of shielded cables for power and I/O connections to the product, but there are no apparent connection points and cables do not appear to have been connected during the tests. Please explain or provide revised user instructions.

Thank you and best regards,

Tim Dwyer
CCS Technical Reviewer

The items indicated above must be submitted before processing can continue on the above referenced application. Failure to provide the requested information within 30 days of the original e-mail date may result in application dismissal and forfeiture of the filing fee. Also, please note that partial responses increase processing time and should not be submitted. Any questions about the content of this correspondence should be directed to the e-mail address listed below the name of the sender.

[Reply](#) [Reply to all](#) [Forward](#) [Invite tim.dwyer@ccsemc.com to Gmail](#)

☆ "tim.dwyer@ccsemc.com" to application [show details](#) Jan 23 [Reply](#) | [▼](#)
- Show quoted text -

[Reply](#) [Reply to all](#) [Forward](#) [Invite tim.dwyer@ccsemc.com to Gmail](#)

☆ from application <application@tw.ccsemc.com> [hide details](#) Jan 28 (4 days ago) [Reply](#) | [▼](#)
to tim.dwyer@ccsemc.com
date Jan 28, 2007 9:40 PM
subject Re:ZIPPY TECHNOLOGY CORP. , FCC ID: P4PBT310, Assessment NO.: AN07T6468, Notice#1

Dear Sir,

Please see my reply, thank you.

Best Regards,

Amanda

<tim.dwyer@ccsemc.com> ???: <application@tw.ccsemc.com>
2007/01/24 09:01 AM ?????:
 ???: ZIPPY TECHNOLOGY CORP. , FCC ID: P4PBT310, Assessment NO.:
 AN07T6468, Notice#1

Dear CCS TW,

The review of this application is complete. Please reply to the following items:

1. Please provide a revised schematic showing the antenna and any circuitry associated with the antenna.
Ans: Please see the revised schematic.

2. The user manual refers to the use of shielded cables for power and I/O connections to the product, but there are no apparent connection points and cables do not appear to have been connected during the tests. Please explain or provide revised user instructions.
Ans: Please see page 4 on the revised userman.

- Show quoted text -

2 attachments — [Download all attachments](#)

 **BT-310 User manual revised 0129.pdf**

81K [View as HTML](#) [Download](#)

 **BT-310 Schematics revised 0129.pdf**

55K [View as HTML](#) [Download](#)

[Reply](#) [Reply to all](#) [Forward](#) [Invite application to Gmail](#)

 from **Tim Dwyer** <Timothy_Dwyer@ieee.org> [hide details](#) Jan 29 (3 days ago) [Reply](#) | ▾

to application <application@tw.ccsemc.com>

cc tim.dwyer@ccsemc.com

date Jan 29, 2007 5:52 PM

subject Re: ZIPPY TECHNOLOGY CORP. , FCC ID: P4PBT310, Assessment NO.: AN07T6468, Notice#1

mailed-by gmail.com

Dear Colleagues,

1. The revised schematic is different from the one originally submitted, but still does not appear to show the antenna and associated RF circuit elements.

2. The revised user manual still includes reference to a shielded power cable on page 4.

Please check again. I think maybe the wrong files were attached to the email

Best regards,

Tim Dwyer

- [Show quoted text](#) -

[Reply](#) [Reply to all](#) [Forward](#)

 **application** to **mike.kuo, tim.dwyer** [show details](#) Jan 31 (1 day ago) [Reply](#) | ▾

- [Show quoted text](#) -

2 attachments — [Download all attachments](#)

 **BT-310 Schematics revised 0129.pdf**

55K [View as HTML](#) [Download](#)

 **BT-310 User manual revised 0129.pdf**

81K [View as HTML](#) [Download](#)

[Reply](#) [Reply to all](#) [Forward](#) [Invite application to Gmail](#)

 from **Mike Kuo** <mike.kuo@ccsemc.com> [hide details](#) 11:58 am (1 hour ago) [Reply](#) | ▾

to Tim Dwyer - TCB <Timothy_Dwyer@ieee.org>,

"Timothy M. Dwyer" <tim.dwyer@ccsemc.com>

date Feb 1, 2007 11:58 AM

subject FW: RE: Re:ZIPPY TECHNOLOGY CORP. , FCC ID: P4PBT310, Assessment NO.: AN07T6468, Notice#1

Hi Tim:

This is reply from the agent.

Best Regards

Mike Kuo

Compliance Certification Services

47173 Benicia Street

Fremont, CA 94538

Direct: (510) 771-1105

Fax: (510) 661-0888

Main: (510) 771-1000

e-mail:mike.kuo@ccsemc.com

Web Site:www.ccsemc.com

From: amanda.wu [mailto:amanda.wu@tw.ccsemc.com]
Sent: Wednesday, January 31, 2007 9:54 PM
To: Mike Kuo
Subject: Re:RE: Re:ZIPPY TECHNOLOGY CORP. , FCC ID: P4PBT310, Assessment NO.: AN07T6468, Notice#1

Dear Mike:

Please help to forward to Mr. Tim. Thank you.

The revised user manual still has shield power cord requirements. Please take a look page 4.
This device has no power cord connector.

Ans: The user manual had been revised on page 4.

The revised schematic diagram still does not show the antenna connecting point and this schematic diagram only contains Power section.

Ans: Provide the schematic for module.

Best Regard

Amanda Wu
Compliance Certification Services Inc.
No. 11, Wu-Kung 6 Rd, Wu-Ku Hsiang,
Wu-Ku Industrial District, Taipei Hsien, (248) Taiwan. R.O.C.
Tel: 886-2-2299-9720 ext: 545
Fax: 886-2-2298-4045

"Mike Kuo"
<mike.kuo@ccsemc.com> ??? : "amanda.wu" <amanda.wu@tw.ccsemc.com>
???? : ?? : RE: Re:ZIPPY TECHNOLOGY CORP. , FCC ID: P4PBT310,
2007/02/01 10:31 AM Assessment NO.: AN07T6468, Notice#1

Amanda:

The revised user manual still has shield power cord requirements. Please take a look page 4.
This device has no power cord connector.

The revised schematic diagram still does not show the antenna connecting point and this schematic diagram only contains Power section.

So you are not answering Tim's questions.

Best Regards

Mike Kuo
Compliance Certification Services
47173 Benicia Street
Fremont, CA 94538
Direct: (510) 771-1105
Fax: (510) 661-0888
Main: (510) 771-1000
e-mail:mike.kuo@ccsemc.com
Web Site:www.ccsemc.com

From: amanda.wu [mailto:amanda.wu@tw.ccsemc.com]
Sent: Wednesday, January 31, 2007 5:19 PM
To: Mike Kuo
Subject: Re:Re:ZIPPY TECHNOLOGY CORP. , FCC ID: P4PBT310, Assessment NO.: AN07T6468, Notice#1

Dear Mike:

?? 1/24????????? 1/31?????? .?? Mr. Tim ?????? .????? .??!

Assessment No:	AN07T6468
FCC ID:	P4PBT310
Certification Scheme	TCB
Grantee Name	ZIPPY TECHNOLOGY CORP.
Application Date	1/23/2007
Administrative Review	
Status	Awaiting Response
Examiner Name	Tim Dwyer
Status Date	1/23/2007
Technical Review	
Status	Awaiting Response
Engineer Name	Tim Dwyer
Status Date	1/23/2007
	Final Status
	Pending
	Reviewer
	Mike Kuo
	Status Date
	1/23/2007

Best Regard

Amanda Wu
 Compliance Certification Services Inc.
 No. 11, Wu-Kung 6 Rd, Wu-Ku Hsiang,
 Wu-Ku Industrial District, Taipei Hsien, (248) Taiwan. R.O.C.
 Tel: 886-2-2299-9720 ext: 545
 Fax: 886-2-2298-4045
 ----- ??? amanda.wu@ccsemc.com 2007/02/01 09:21 AM -----

application
 ????: ????: <tim.dwyer@ccsemc.com>, mike.kuo@ccsemc.com
 amanda.wu
 ?????:
 ???: Re:Re:ZIPPY TECHNOLOGY CORP. , FCC ID: P4PBT310, Assessment NO.:
 ??? AN07T6468, Notice#1 ? ?
 2007/01/31
 01:22 PM
 - Show quoted text -

2 attachments — [Download all attachments](#)

-  **BT-310 User manual revised 0201.pdf**
81K [View as HTML](#) [Download](#)
-  **BT-310 Schematics for module revised 0201.pdf**
77K [View as HTML](#) [Download](#)