

INTERTEK TESTING SERVICES

Report No.: 0311891
Model No.: #10750

Pursuant to FCC Part 15 Section 15. 235 Emissions Requirement


PLT: 56.72ms

-0.05dB

RB 3MHz# AT 10dB

RLV: 97.00dBuV

VB 3MHz



Tested By: KL
(Kenneth Wong)

Date: 21/7/03

Checked By: [Signature]
(Anthony Chan)

Date: 25/7/03

Test Result: Pass / Fail / NA

DT: 0us

TS: 90ms

F: 49.860000MHz

INTERTEK TESTING SERVICES

Report No.: 031891
Model No.: #10750

Pursuant to FCC Part 15 Section 15. 235 Emissions Requirement


PLT: 36.60ms

-0.01dB

RB 3MHz# AT 10dB

RLV: 97.00dBuV

VB 3MHz



Tested By: KL
(Kevin Wong)
Date: 2/17/03

Checked By: [Signature]
(Kerry Chen)
Date: 2/17/03

Test Result: Pass / Fail / NA

DT: 0us

TS: 50ms

F: 49.660000MHz

Report No.: 031891
Model No.: #10750

Pursuant to FCC Part 15 Section 15. 235 Emissions Requirement


DLT: 1.40ms

-0.08dB

RB 3MHz# AT 10dB

RLV: 97.00dBuV

VB 3MHz



Tested By: KA
(Kernel Wang)

Date: 21/7/03

Checked By: [Signature]
(Denny Chan)

Date: 25/7/03

Test Result: Pass / Fail / NA

DT: 0us

TS: 50ms

F: 49.850000MHz

Report No.: 0311891
Model No.: #10750

Pursuant to FCC Part 15 Section 15.245 Emissions Requirement


PLT: 100us

-0.09dB

FB 3MHz# AT 10dB

RLV: 97.00dBuV

VB 3MHz



DT: 0us

TS: 50ms

F: 49.860000MHz

Tested By: LA
(Grove Winy)
Date: 2/17/03

Checked By: [Signature]
(Anthony Lam)
Date: 25/7/03

Test Result: Pass / Fail / NA