

Chris Harvey

From: Chris Harvey
Sent: Monday, April 29, 2002 11:16 AM
To: 'alice_wong@hkstc.com'
Cc: Marianne Bosley
Subject: #12259 Lung Cheong FC ID: P73KGRACER49TX

Alice, below are 2 technical items that need to be corrected for the referenced application:

- 1) The Schematic Diagram is not correct. Please provide the correct diagram.
- 2) The Duty Cycle correction factor is stated using 2 different numbers on pages 10 and 17 (of 20). Please verify which number is correct and ensure that the data has been corrected properly.

This application will be continued upon receipt of this information.

Best regards,

Chris Harvey

Chris Harvey

EMC Lab Director, MET Laboratories, Inc.
1-800-638-6057 x-310
charvey@metlabs.com

Chris Harvey

EMC Lab Director, MET Laboratories, Inc.
1-800-638-6057 x-310
charvey@metlabs.com