

10/28/01
November 1, 2001

Bay Area Compliance

In reference to FCC ID: PERWT402

Mr. Chan

[Mr. Case](#)

Upon completion of review of the Family Radio Service application FCC ID: PERTW402, there are several issues that must be addressed before the application can be granted by ATCB.

Please address each issue below.

- 1) Please verify that the hand held device was tested in all three orthogonal planes.

[Yes. The band held device was tested in all three orthogonal planes.](#)

- 2) Please list the value of the maximum audio frequency response that was measured.

[The value of the maximum audio frequency response that was measured is 7.5dB. Please see the attached plot for more information.](#)

- 3) For the occupied Bandwidth test, please provide the justification for the 3750 Hz tone used instead of a 2500 Hz tone used and please verify that the modulation was not effected by audio noise from the transmitter itself.

[Yes. We verify that the modulation was not effected by audio noise from the transmitter itself. Please see the attached plot for more information.](#)

Regards

David A. Case NCE
Examining Engineer
<mailto:dcase@AmericanTCB.com>

[John Chan](#)

[Engineering Manager](#)

The items indicated above must be submitted before processing can continue on the above referenced application. Failure to provide the requested information may result in application termination.

Correspondence should be considered part of the permanent submission and may be viewed from the Internet after a Grant of Equipment Authorization is issued.

Please do not respond to this correspondence using the email reply button. In order for your response to be processed expeditiously, you must submit your documents through the AmericanTCB.com website. Also, please note that partial responses increase processing time and should not be submitted.

Any questions about the content of this correspondence should be directed to the sender.

