

Wistron Corporation

21F., No. 88, Sec. 1, HsinTai 5th Rd., Hsichih Dist, New Taipei City 221, Taiwan

Tel: +886-2-66121641 ; Fax: +886-2-66122188

To whom it may concern:

This device with FCC ID: PU5-TP00076BUC/ IC: 4182A-TP00076BUC integrates a Wi-Fi/BT module:

| | Brand | FCC ID | IC ID |
|-----------------|-------|-----------|--------------|
| Wi-Fi/BT module | Intel | PD98260NG | 1000M-8260NG |

No hardware design changes are made on the modules, and the software has not been changed to increase the RF output power of the modules. Pursuant to KDB 996369 D01v02, the original modular report (Report Number:

SAR.20151009/1540055R-RFUSP05V00-A/1540055R-RFUSP05V00/1540055R-RFUSP01V00/1540055R-RFUSP01V00-A/1540055R-RFUSP01V00-B/1540055R-RFCAP05V00-A/1540055R-RFCAP05V00/1540055R-RFCAP01V00/1540055R-RFCAP01V00-A/1540055R-RFCAP01V00-B/1570011S-CUSTOM/1570011S-CUSTOM-A) are submitted to represent the compliance of Part 2/15C/15E /RSS-102/RSS-247 testing items of this device.

Should you have any comments or questions, please feel free to contact me.

Sincerely,



Eric Shu

eric_shu@wistron.com