



Annex B of test report F092137E1
EUT: cB-0925-01-1-0x
Manufacturer: connectBlue AB



92137_d.jpg

cb-0925-01-1-02, top view


Annex B of test report F092137E1
EUT: cB-0925-01-1-0x
Manufacturer: connectBlue AB



92137_e.jpg

cB-0925-01-1-01, top view


Annex B of test report F092137E1
EUT: cB-0925-01-1-0x
Manufacturer: connectBlue AB



92137_g.jpg

cB-0925-01-1-01, shielding removed, top view


Annex B of test report F092137E1
EUT: cB-0925-01-1-0x
Manufacturer: connectBlue AB




92137_g.jpg

cB-0925-01-1-0x, bottom view

Annex B of test report F092137E1
EUT: cB-0925-01-1-0x
Manufacturer: connectBlue AB




Annex B of test report F092137E1
EUT: cB-0925-01-1-0x
Manufacturer: connectBlue AB



92137_b.jpg

cB-0903-02, carrier board, top view

Annex B of test report F092137E1
EUT: cB-0925-01-1-0x
Manufacturer: connectBlue AB



92137_c.jpg

cB-0903-02, carrier board, bottom view