



Vår handläggare, namn, tfn • Attending to this matter, name, telephone

Confidential

Ert datum • Your date

Er beteckning • Your reference

Prepared by
SEM/BGLIVM Afrah Sadiq + 46 10 80 12250
Contents responsible if other than preparer

Document number
BGLI08:842
Date
2008-09-30
Remarks

Revision
A

Approved by
SEM/BGLIVMC Peter Lindeborg + 46 10 80 16180

Receiver: Federal Communication Commission and
Certification and Engineering Bureau
Industry Canada

**Application: PY7A1052151,
4170B-A1052151.**

Statement on Bluetooth hardware

Sony Ericsson mobile phone C905c (FCC ID: PY7A1052151, IC: 4170B-A1052151) uses the exact same Bluetooth hardware and software as C905 (FCC ID: PY7A3352021, IC: 4170B-A3352021).

Based on this, FCC part 15.247 and RSS – 210 Issue 7 report (report no. 2-4883-46-04/08, dated 2008-07-14) issued for C905 also applies for C905c.

Best regards,

Peter Lindeborg

Technical Manager – EMF and Safety

Sony Ericsson Mobile Communications AB - Lund

Sony Ericsson Mobile Communications AB

Postadress • Mail
SE-221 88 Lund
Sweden

Besöksadress • Office address
Nya Vattentornet
Lund

Styrelsens säte: Lund
Registered office: Lund
Telefon • Telephone
Nat 046-19 40 00
Int +46 46 19 40 00

Momsnr • V.A.T.No: SE556615665801
Organisationsnr • Reg No: 556615-6658
Telefax • Telefax
Nat 046-19 41 00
Int +46 46 19 41 00