



Sony Ericsson

Confidential

1(1)

Prepared by

SEMC/CVDVBA Afrah Sadiq + 46 10 80 12250

Contents responsible if other than preparer

Document number

CVDVBA11:194

Date

2011-06-08

Remarks

Revision

A

Approved by

SEMC/CVDVBA Johan Wedin Svensk tel +46 10 80 11987

Receiver: Federal Communication Commission and
Certification and Engineering Bureau
Industry Canada

Application: Type number: AAB-1880034-BV,

FCC ID: PY7A1880034,

Canada IC: 4170B-A1880034

Statement on Bluetooth hardware

Sony Ericsson mobile phone CK15a (FCC ID: PY7A1880034, IC: 4170B-A1880034) uses the exact same Bluetooth hardware and software as CK15i (FCC ID: PY7A1880031, IC: 4170B-A1880031).

Based on this, FCC part 15.247 and RSS – 210 Issue 7 report (report no. 1-2977-21-04/11-A, dated 2011-05-23) issued for CK15i also applies for CK15a.

Best regards,

Johan Wedin Svensk
Manager GSM/UMTS
Sony Ericsson Mobile Communications (Sweden)AB

Sony Ericsson Mobile Communications AB

Postadress • Mail
SE-221 88 Lund
Sweden

Besöksadress • Office address
Nya Vattentornet
Lund

Styrelsens säte: Lund
Registered office: Lund
Telefon • Telephone
Nat 046-19 40 00
Int +46 46 19 40 00

Momsnr • V.A.T.No: SE556615665801
Organisationsnr • Reg No: 556615-6658
Telefax • Telefax
Nat 046-19 41 00
int +46 46 19 41 00