



Vår handläggare, namn, tfn - Attending to this matter, name, telephone number, date

Confidential

Ert datum • Your date

Er beteckning • Your reference

Document number

BGLI08:902

Date

2008-10-31

Remarks

Revision

A

Prepared by

SEM/BGLIVM Afrah Sadiq + 46 10 80 12250

Contents responsible if other than preparer

Approved by

SEM/BGLIVMC Peter Lindeborg + 46 10 80 16180

Receiver: Federal Communication Commission and Certification and Engineering Bureau Industry Canada

Application: PY7A3252081,
4170B-A3252081.

Statement on Bluetooth hardware

Sony Ericsson mobile phone G705a (FCC ID: PY7A3252081, IC: 4170B-A3252081) uses the exact same Bluetooth hardware and software as G705u (FCC ID: PY7A3352031, IC: 4170B-A3352031).

Based on this, FCC part 15.247 and RSS – 210 Issue 7 report (report no. 2-4883-53-06/08, dated 2008-09-19) issued for G705u also applies for G705a.

Best regards,

Peter Lindeborg

Technical Manager – EMF and Safety

Sony Ericsson Mobile Communications AB - Lund

Sony Ericsson Mobile Communications AB

Postadress • Mail
SE-221 88 Lund
Sweden

Besöksadress • Office address
Nya Vattentornet
Lund

Styrelsens säte: Lund
Registered office: Lund
Telefon • Telephone
Nat 046-19 40 00
Int +46 46 19 40 00

Momsnr • V.A.T.No: SE556615665801
Organisationsnr • Reg No: 556615-6658
Telefax • Telefax
Nat 046-19 41 00
Int +46 46 19 41 00