

6 Annex B: Photographs of Test site

Photo 1 (Radiated Spurious emission)




Photo 2 (Radiated Spurious emission)





Photo 3 (Conducted radiated Emissions):



7 Annex C: External Photographs of the Equipment

Photo Nr.: 01



Photo Nr.: 02



8 Annex D: Internal Photographs of the Equipment



CETECOM ICT Services GmbH

Untertürkheimer Str. 6-10, 66117 Saarbruecken
RSC-Laboratory

Phone: +49 (0) 681 598-0
Phone: +49 (0) 681 598-0

Fax: -9075
Fax: -9075

Annex to Test report no.: 2-4094-17-02/05 Date: 2006-02-03

Page 26 of 32

Photo Nr.: 02



Photo Nr.: 03



Photo Nr.: 04



Photo Nr.: 05



CETECOM ICT Services GmbH

Untertürkheimer Str. 6-10, 66117 Saarbruecken
RSC-Laboratory

Phone: +49 (0) 681 598-0
Phone: +49 (0) 681 598-0

Fax: -9075
Fax: -9075

Annex to Test report no.: 2-4094-17-02/05


Date: 2006-02-03

Page 30 of 32

Photo Nr.: 06



Photo Nr.: 07



CETECOM ICT Services GmbH

Untertürkheimer Str. 6-10, 66117 Saarbruecken
RSC-Laboratory

Phone: +49 (0) 681 598-0
Phone: +49 (0) 681 598-0

Fax: -9075
Fax: -9075

Annex to Test report no.: 2-4094-17-02/05 Date: 2006-02-03

Page 32 of 32

Photo Nr.: 08

