



LINKSYS®
A Division of Cisco Systems, Inc.

Cisco-Linksys LLC

**121 Theory Drive Irvine, CA 92617(USA)
Phone: (949) 910-7048 Fax: (949) 823-3002**

Date:2009/12/9

Federal Communications Commission
7435 Oakland Mills Road
Columbia, MD21046

Attention: Application Examiner/Review Engineer

Subject: Request to change in identification per section 2.933 of FCC rules

To The Commission:

This Change of Identification request applies for a new FCC ID as established in 47CFR 2.933(b) for a currently approved device. This application by Cisco-Linksys LLC will establish a new FCC ID under Cisco-Linksys LLC 's. grantee code for purpose of marketing. The original grant to Cisco-Linksys LLC. EUT name: Wireless-N USB Network Adapter with Dual-Band, Model Number: WUSB600N ver.2, FCC ID: Q87-WUSB600NV2 will remain in effect.

An authorization letter by Cisco-Linksys LLC is attached.

Per 2.933(b)

1. The original identification is (FCC ID number: Q87-WUSB600NV2)
2. The original grant date is 05/11/2009
3. The equipments is electrically identical. Only the model name , and FCC ID number are different.
4. The original test results are applicable and representative of this changed device.
5. Exterior photographs are included in this application.

The following files are electronically submitted as attachments:

Cover Letter

External Photos

FCC ID label format and location

Best Regards,

Darrell Tennis / Manager Compliance
Cisco-Linksys LLC
Phone: 949-910-7048
Fax: 949-823-3002
dtennis@cisco.com