

Prüfbericht - Nr.: 17002467 001
Test Report No.

Seite 1 von 28
Page 1 of 28

Appendix E


Field Strength of Spurious Radiation Measurements

According to CFR 47 (FCC) part 2.1053

The Result of Spurious Radiation Test

1. BTS3601C Test Result

1 carriers have been work normally. BTS work at frequency No.283(878.49MHz).




Prüfbericht - Nr.: 17002467 001

Test Report No.

Seite 3 von 11

Page 3 of 11




The point which exceeds the limit line is the carrier frequency.

Prüfbericht - Nr.: 17002467 001

Test Report No.


Seite 4 von 11

Page 4 of 11




Prüfbericht - Nr.: 17002467 001
Test Report No.

Seite 5 von 11
Page 5 of 11



The Result of Substitute Test



Prüfbericht - Nr.: 17002467 001


Test Report No.


Seite 7 von 11

Page 7 of 11

2. ODU3601C Test Result

1 carriers have been work normally. BTS work at frequency
No.283(878.490MHz).






The point which exceeds the limit line is the carrier frequency.


Prüfbericht - Nr.: 17002467 001
Test Report No.

Seite 9 von 11
Page 9 of 11



Prüfbericht - Nr.: 17002467 001
Test Report No.

Seite 10 von 11
Page 10 of 11




Prüfbericht - Nr.: 17002467 001

Test Report No.

Seite 11 von 11

Page 11 of 11

The Result of Substitute Test



END