



anson.lu

2009/12/21 11:10 AM

收件人： gina.lo/ccsemc@ccsemc

副本抄送：

主旨： 回信： Response to Inquiry to FCC (Tracking Number 721321)



oetech@fccsun27w.fcc.gov



oetech@fccsun27w.fcc.gov

2009/07/17 10:23 PM

收件人： anson.lu@ccsrf.com

副本抄送：

主旨： Response to Inquiry to FCC (Tracking Number 721321)



[FCC Home](#) | [Search](#) | [Updates](#) | [E-Filing](#) | [Initiatives](#) | [For Consumers](#) | [Find People](#)

Office of Engineering and Technology

Inquiry:

How are you doing?<?xml:namespace prefix = o ns = "urn:schemas-microsoft-com:office:office" />

We have a doubt for simultaneous SAR evaluation about the Notebook Computer
Could you please be kind to let us know if the Simultaneous SAR evaluation is necessary for this Notebook Computer?

If need, Is simultaneous SAR evaluation follow KDB616217 ?

Best regards and have a nice day.

Response:

For this specific laptop configuration with display smaller than 12 inch, this KDB response serves to allow use of KDB 616217 procedures to determine RF exposure procedures.

Applicant and/or test lab are responsible to apply KDB 616217 analysis using applicable source-based time-averaged conducted powers, and which must be reviewed and verified by reviewer during equipment authorization application processing.

Do not reply to this message. Please select the [Reply to an Inquiry Response](#) link from the OET Inquiry System to add any additional information pertaining to this inquiry.

This e-mail transmission is confidential and intended solely for being reviewed by the recipient(s) identified above. If you are not an identified recipient, please ensure that this communication remains confidential and promptly return it to the sender. Please contact

This e-mail transmission is confidential and intended solely for being reviewed by the recipient(s) identified above. If you are not an identified recipient, please ensure that this communication remains confidential and promptly return it to the sender. Please contact immediately by phone (Tel: 886-2-2299-9720) for any problem with this transmission. Thank you for your attention.