



Date: 18/4/13

attn: Reviewing Engineer  
Federal Communications Commission  
7435 Oakland Mills Road  
Columbia, MD 21046

To Whom It May Concern:

The Nayax Ltd. VPOS Reader NAYAXVPOS5, FCC ID: R88NYXA3V and label is so small that it cannot include the statement specified in FCC Part 15 Sub-part A, Section 15.19 (a) (3)

"This device complies with Part 15 of the FCC Rules. Operation is subject to the following two conditions:

- (1) This device may not cause harmful interference and
- (2) This device must accept any interference received, including interference that may cause undesired operation."

Due to this reason, we are using the provisions of Part 15 Sub-part A, Section 15.19 (a) (5) and this statement appears in a prominent location in the user manual.

Please contact me if there is any information you may need.



Thank you,



Hezi Cohen  
Chief Operating Officer  
Nayax Ltd.

---

Nayax Ltd. 24 Raoul Wallenberg St., Building A1, 4th floor Tel Aviv, 69710, ISRAEL

 Tel: +972 (3) 7694334  Fax: +972 (3) 7694344