



American Telecommunications Certification Body Inc.
6731 Whittier Ave, McLean, VA 22101

December 26, 2003

RE: FCC ID: RLN895662_ATCB001011

Attention: Mike Royer

I have a few comments on this Application.

1. Please note that RNL is the grantee code not the equipment code. Please put the correct equipment code on the 731 form under item 4a. FHSS devices are DSS and DSSS devices are DTS.
2. Please note that this device has not been tested in accordance with the requirements of 15.247. As such the device is considered to fail. Please resubmit a report that is in full compliance to the requirements of 15.247 using the accepted FCC test procedure found in DA000705 FHSS.

Dennis Ward

<mailto:dward@AmericanTCB.com>

The items indicated above must be submitted before processing can continue on the above referenced application. Failure to provide the requested information may result in application termination. Correspondence should be considered part of the permanent submission and may be viewed from the Internet after a Grant of Equipment Authorization is issued.

Please do not respond to this correspondence using the email reply button. In order for your response to be processed expeditiously, you must submit your documents through the AmericanTCB.com website. Also, please note that partial responses increase processing time and should not be submitted.

Any questions about the content of this correspondence should be directed to the sender.