

STANDARD OPERATION SHEET PS001480

Process: Fit FCC label

Issued by: N Holland

H&S:

Product: 5276

Issue: 1

Training: Refer to training matrix.

Job Number:

Print date:

Step	Action	Quality/Parameters	Tools/equipment	Photo/Diagram
1	Attach FCC label to PCB as indicated	Label Specification Matt White PE Perm PE= Backing paper type	527602 (PCB) LB054 (label)	

Signature

Uncontrolled Document when printed

INT 47/8

Distribution: D.O. Jabil China

Page 1 of 1