



Suite 230
2891 Sunridge Way NE
Calgary, Alberta
Canada T1Y 7K7
Tel (403) 777-3760
Fax (403) 777-3769
www.mentoreng.com

Federal Communication Commission
Equipment Authorization Division, Application Processing Branch
7435 Oakland Mills Road
Columbia, MD 21048

January 25, 2005

TO WHOM IT MAY CONCERN

Mentor Engineering's models: MultiConnect 1xRTT and BBx 1xRTT have a built-in dual band CDMA modem which is in all hardware and software aspects identical (unmodified) to the previously certified device FCC ID: RZ3MDC0V01 used in the model MDC 1xRTT. Therefore, the test results prepared by Intertek from test report 30693501 issued on 12/27/04 are applicable to the models MultiConnect 1xRTT and BBx 1xRTT.

Sincerely,

A handwritten signature in blue ink, appearing to read "S. Hickle", with a stylized flourish at the end.

Stephen Hickle
Director

Mentor Engineering Inc.
Suite 503, 609-14th Street N.W.
Calgary, AB. Canada T2N 2A1
Ph:(403) 777-3760 (ext 826) Fax:(403) 777-3769
E-mail: shickle@mentoreng.com
Website: www.mentoreng.com

MDC Family Attributes

attribute	MDC	MultiConnect	BBX
RF module	FCC ID: 09EQ2438F	FCC ID: 09EQ2438F	FCC ID: 09EQ2438F
Display	LCD	LED	LED
Enclosure	plastic	plastic	plastic
Ports	Smart Card, PC Card, 4 COM	COM	USB, COM
GPS	yes	no	yes
Memory	Flash, RAM	no	Flash, SDRAM
I/O	Digital, Analog, Odometer	no	Digital, Analog, Odometer
Interfaces	optional J-1708, J-1850	no	optional J-1708