

Invixium Access Inc.
Address: 300-111 Gordon Baker Road, Toronto, Canada M2H 3R1
Tel: 1-416-414-0736
Fax: 1-844-468-4948
Email: vlazic@invixium.com

FEDERAL COMMUNICATIONS COMMISSION
Authorization and Evaluation Division
7435 Oakland Mills Road
Columbia, MD 21046

Subject: Request to change in Identification.

Date: 2023-09-26

Dear Regulatory Authority,

This Change of Identification request applies for a new FCC ID: S38-IXMC410 as established in 47CFR2.933(b) for a currently approved device. This application by Invixium Access Inc. will establish a new FCC ID: S38-IXMC410 under Thundercomm Technology Co., Ltd grant code for purpose of marketing, and the new model will be under new FCC ID. The original grant to Thundercomm Technology Co., Ltd (FCC ID: 2AOHHTURBOXC610) will remain in effect.
Per 2.933(b)

1. The original identification is Thundercomm Technology Co., Ltd (FCC ID: 2AOHHTURBOXC610)
2. The original grant date is: 02/16/2021
3. The equipment is electrically identical, only the FCC ID number, applicant name and address, product name, model number, brand are different.
4. The original test results are applicable and representative of this changed device.
5. Exterior photographs are included in the application.

The following files are electronically submitted as attachments:

Cover letter

External photos

FCC ID Label format and location

Sincerely,

Signature:



Vladimir Lazic

Principal Engineer