

Hello Tim,

Please see the response below.

1. The GSM can not co-locate with BT. Therefore, the MPE will not calculating MPE for co-location of GSM and BT.
2. The updated Block Diagram has been uploaded. And the updated IC form with designator for BT was uploaded last time.
Please check it.

Thank you very much.

Best Regards,

Ivonne