

## Correspondence by Project

### Project Number:

-1083522937

Correspondence Number	Memo
SWW2112S-1	<p>1) Since the two-condition statement contained in section 15.19(a)(3) does not appear on the device's label, the statement must be included in the user's manual. Please submit a revised manual. Response: The Owners Manual has been Revised to Include this Statement.</p> <p>2) The operational description states that the device uses frequencies of 4.9152 MHz and 8 MHz, which do not appear in the block diagram. As per section 2.1033(b)(5) of the FCC rules, the block diagram must show "the frequency of all oscillators used in the device. The signal path and frequency shall be indicated at each block. The tuning range(s) and intermediate frequency(ies) shall be indicated at each block." Please submit a revised diagram. Response: The EUT only operates at 4.9152 MHz and NOT at 8 MHz. The 8 MHz was what the processor can go up to, but will never be operated at this speed. The Hardware Theory of Operation and Block Diagram have been revised.</p>